



Horton Emergency Vehicles--3800 McDowell Rd.--Grove City, OH 43123

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC

Year: 2015
Chassis: Navistar 102"
Type: MED
Model: CCO 102"
Rev 1 Print Features **11840**

CATEGORIES:

- A** Chassis
- B** Body Connection Pass Thru Type
- BH** Chassis Accessories
- BL** Chassis Electrical
- C** Conversion Model
- CB** Module Body Modifications
- D** Module Body Hardware
- E** Paint and Striping
- F** Cabinet Doors, Handles and Hardware
- G** Interior Colors
- H** Interior Cabinets, Streetside
- I** Interior Cabinets, Curbside
- J** Front Wall Cabinets
- K** Interior Accessories and Trim
- L** Cot Mount, and Patient Handling
- M** Warning Systems, Visual
- MN** Warning Systems, Audible
- O** Lights, Non Emergency
- P** Electrical Power Group
- Q** Heat, Ventilation, Air conditioning
- R** Console, Radio, and communications
- T** Oxygen and Suction
- U** Lettering and Graphics
- Z** Other

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

AA00000C 1 1 SPECIFICATION FOR AN AMBULANCE BODY RECHASSIS

!!! 623 CONVERSION !!!

AB **Horton Emergency Vehicles Feature List**

AB000001 1 1 ORIGINAL CONVERSION INFORMATION

Original info is as follows:

CONVERSION INFO.

Original Horton I.D. #TBD

Model: 603

Type: I

Cab to Axle: 102"

Body Length: 167"

Body Width: 96"

Interior Height: 72"

Cab Connection Type: Walkthrough_____ Bellows__X__

Body Mount Style: Double Bolt Style__X__ ViTech _____

Fuel Fill Location: CAB

Electrical System: INTELLIPLEX

CHASSIS INFO.

Year: TBD

Make: INTERNATIONAL

Model: 4300

Miles: TBD

VIN: TBD

AB000002 1 1 RETURN ITEMS

The following items shall be returned to the customer:

Used chassis returned: _____

Used chassis disposed of by Horton: __X__

!!! TITLE TO BE PROVIDED AT DROP-OFF.

AC **CHASSIS**

AI **NAVISTAR CHASSIS**

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

AIN12014 0 1 CHASSIS, 2014 NAVISTAR 4300LP, 102" C/A

The chassis required to complete the ambulance conversion shall be supplied by Horton. All chassis ordered with OEM air rides will include a Horton installed air tank drain line, running from the tank(s) to the bottom side of the rub rail.

!!! 2015 MODEL

Reference quote #: 746-01

CHASSIS TO BE PURCHASED THROUGH WARD INTERNATIONAL OF PENSACOLA, FL.

AJNSPIC0 1 1 CHASSIS INTERIOR COLOR SHALL BE GRAY

B CHASSIS MODIFICATIONS, HARDWARE AND ACCESSORIES

BH02F000 1 1 HUB & LUG NUT COVERS, STAINLESS FOR NAVISTAR 19.5"

Polished stainless steel hub and lug nut covers shall be installed on all four outside wheels.

BH02H000 1 1 TIRE SIZE, 19.5", MEDIUM DUTY:

This vehicle is specified to have 19.5" tires.

BH02J000 0 1 CHASSIS IS EQUIPPED WITH AIR BRAKES:

This vehicle is specified to have air brakes. Note that proper tire clearances are allowed.

!!! NOTE PREVIOUS CHASSIS HAD HYDRAULIC BRAKES. BODY MODIFICATION MAY BE REQUIRED.

BH040000 1 1 CHASSIS IS EQUIPPED WITH HORIZONTAL EXHAUST

The chassis specified above is to include a horizontal exhaust.

The exhaust will exit on the drivers side of the vehicle unless otherwise noted.

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

- BH04F000 1 1 CHASSIS HORSEPOWER RATING IS LESS THAN 260HP**
The chassis specified above will have the standard cab height.
Note: Engines with less than 260 hp may have raised cab due to cooling package and larger radiator.
- BH26K000 0 1 TRANSFER FUEL TANK COVERS**
Transfer the existing diamondplate fuel tank covers to the new chassis.
- BH32OR00 1 1 AIR SUSPENSION SWITCH: dump override**
A switch will be installed where specified, to override the automatic dump feature activated by the left rear patient compartment entry door.
!!! INSTALL NEW STYLE INTELLIPLEX SWITCH PANEL AT ORIGINAL LOCATION.
- BL26L000 0 1 DUAL PURPOSE CAMERA SYSTEM, BACKUP AND PATIENT AREA VEWING**
Install a Voyager VCCS150 backup camera over the rear doors. Install a second camera on the interior of the vehicle as noted below. Install a Voyager AOM711 7" LCD screen in the cab rearview mirror area. Wire to activate the backup camera when the vehicle is placed into reverse. The second camera is to provide a view of the patient area when selected.
INTERIOR CAMERA LOCATION: STD
!!! TRANSFER THE EXISTING REAR CAMERA AND CABLE.
- BL32A000 1 1 OEM AM/FM/CD PLAYER SHALL BE PROVIDED BY THE OEM MANUFACTURER**
OEM AM/FM/CD player shall be provided by the OEM manufacturer on all Horton supplied chassis.
Note: This option applies only to chassis supplied by Horton. Chassis supplied by either the customer or the dealer must be ordered with this feature from the chassis OEM.
- BSP00001 0 1 SPECIAL INSTRUCTION, CHASSIS MODIFICATION HARDWARE & ACCESSORIES**
!!! TRANSFER DRIVECAM SYSTEM TO NEW CHASSIS.



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

| <u>Option</u> | <u>Std</u> | <u>Qty</u> | <u>Header/Description/Data</u> | <u>Proposal Total</u> |
|---------------|------------|------------|--------------------------------|-----------------------|
|---------------|------------|------------|--------------------------------|-----------------------|

| | | | | |
|----------|---|---|---|--|
| BSP00002 | 0 | 1 | SPECIAL INSTRUCTION, CHASSIS MODIFICATION HARDWARE & ACCESSORIES | |
|----------|---|---|---|--|

!!! TRANSFER AND CLEAN THE EXISTING REAR STEP. NOTIFY SPECWRITER IF THERE IS ANY DAMAGE TO THE STEP.

| | |
|-----------|------------------|
| C1 | RECHASSIS |
|-----------|------------------|

| | | | | |
|----------|---|---|------------------------|--|
| CA900000 | 0 | 1 | BASE CHANGEOVER | |
|----------|---|---|------------------------|--|

Existing ambulance body is to be remounted onto a new chassis. Perform inspection of body and communicate any areas of concern to the customer.

| | | | | |
|----------|---|---|--|--|
| CB100000 | 1 | 1 | BODY TO CHASSIS TIE DOWNS & CAB TO BODY SEAL OR BELLOWS | |
|----------|---|---|--|--|

All new body to chassis tie downs shall be installed. Tie downs to be same style as original. Also a new cab to body seal or bellows shall be installed. Whichever is applicable

| | | | | |
|----------|---|---|---|--|
| CB250500 | 0 | 3 | REPLACE ENTRY DOOR HANDLES, EACH | |
|----------|---|---|---|--|

Upgrade entry door Trimark handles, and linkage to current standards. New inside door panel included.

Doors: ALL ENTRY DOORS.

!!! INSTALL NEW STYLE EMERGENCY DOOR RELEASE LATCHES ON THE REAR ENTRY DOORS.

| | |
|----------|-----------------------------|
| D | MODULE BODY HARDWARE |
|----------|-----------------------------|

| | | | | |
|----------|---|---|---|--|
| DG030000 | 0 | 1 | COMPARTMENT AND ENTRY DOOR SEALS | |
|----------|---|---|---|--|

All entry door and compartment door seals shall be replaced.

| | | | | |
|----------|---|---|---|--|
| DH03A000 | 0 | 2 | REPLACE FRONT STAINLESS STEEL SPLASH SHIELDS | |
|----------|---|---|---|--|

Replace the stainless steel splash shields with new brushed stainless material.

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

- DH04A000 0 1 REPLACE MODULE BODY FENDERS: stainless steel**
Rear wheel housings shall have new stainless steel flare skirts to protect the wheel house opening and side body finish.
- DH04RS20 0 4 REPLACE DIAMOND PLATE RUB RAIL, EACH**
Replace the diamond plate rub rail at the described location.
Locate:
- DH110000 0 4 REPLACE DIAMOND PLATE CORNER GUARD, EACH**
Replace the diamond plate corner guard at the described location.
Locate:
- DH420000 0 1 REPLACE THE DIAMOND PLATE RISER**
Replace the rear diamondplate riser between the bottom of the rear entry door opening and the bottom of the body.
- DSP00001 0 1 SPECIAL INSTRUCTION, MODULE BODY HARDWARE**
!!! REMOVE EXISTING SIDE DOOR STEP AND INSTALL A ZICO STEP TO MATCH NEWER UNITS.

E1 PAINT AND STRIPING

- ED00000C 0 1 COMPLETE REPAINT**
1. Remove all body doors, door handles, hinges, windows and hardware
2. Sand body and doors
3. Acid etch body and doors
4. Apply conversion coating
5. Repaint body and doors per color instructions listed below
6. Reinstall doors, door handles, hinges, windows and hardware unless new parts are specified
- ED010000 1 1 CHASSIS PAINT: standard white**
Chassis color to be standard white.

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

| Option | Std | Qty | Header/Description/Data | Proposal Total |
|--------|-----|-----|-------------------------|----------------|
|--------|-----|-----|-------------------------|----------------|

| | | | | |
|----------|---|---|---|--|
| ED04A000 | 0 | 1 | MODULE PAINT: standard white Paint module standard white Sikkens #FLNA4002. <i>Note: This option applies only when repaint option is chosen above.</i> | |
|----------|---|---|---|--|

| | | | | |
|----------|---|---|---|--|
| ED090000 | 0 | 1 | STRIPE: custom Special paint stripe See drawing <i>!!! DUPLICATE EXISTING STRIPE.</i> | |
|----------|---|---|---|--|

| | |
|----------|---|
| F | INTERIOR CABINET DOORS, HANDLES & HARDWARE |
|----------|---|

| | | | | |
|----------|---|---|---|--|
| FE010001 | 1 | 1 | INSPECT CABINET DOORS, HANDLES & HARDWARE All Interior cabinet latches, hinges, doors, handles, sliders, hardware and trim to be inspected, and replaced as required. Replacement of parts will be at an extra cost and must be approved prior to replacement. <i>!!! REPLACE ANY DISCOLORED OR WORN CABINET HINGES/LATCHES.</i> | |
|----------|---|---|---|--|

| | | | | |
|----------|---|---|---|--|
| FE08SU00 | 0 | 1 | REPLACE INHALATION PANEL Replace the existing inhalation panel with a new panel fabricated from Coosa material and covered with Formica to match the interior color. <i>!!! INSTALL A STANDARD ANGLED PANEL TO MATCH 15660. CUT SHORT 14" FOR MONITOR BRACKET.</i> | |
|----------|---|---|---|--|

| | |
|-----------|--|
| G1 | INTERIOR COLORS, UPHOLSTERY AND SEATING |
|-----------|--|



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

| <u>Option</u> | <u>Std</u> | <u>Qty</u> | <u>Header/Description/Data</u> | <u>Proposal Total</u> |
|---------------|------------|------------|--------------------------------|-----------------------|
|---------------|------------|------------|--------------------------------|-----------------------|

GF00000C 0 1 REPLACE MODULE FLOOR MATERIAL

Remove and replace entire patient area floor with new material. Option includes the following:

1. New floor material
2. New sub floor
3. Remove attendant seat base, vertical cabinet and front wall cabinet
4. Reinstall existing cot floor hardware (unless new hardware is selected)
5. Reinstall rear, side door and cab stainless steel thresholds (Unless new material is selected)

Flooring material required: LONCOIN FLECKSTONE SAPPHIRE #152

GF00001C 0 1 REPLACE ALL INTERIOR UPHOLSTERY

Replace all interior upholstery with water fall style cushions and backrests. Include bench cushions, CPR seat, hip cushions, backrests, and head bumpers. Install new closeouts.

Color: FLINT GRAY

Note: Does not include bucket seats.

GK12A100 0 1 NEW SEAT BASE FOR BOXED SEAT

A boxed seat base shall be located at the head of the cot. The base shall be fabricated from aluminum.

!!! BASE TO BE USED WITH SEAT LISTED BELOW. BASE TO BE USED TO HOUSE THE RADIOS. VENT BASE ADEQUATELY FOR RADIO STORAGE. DUPLICATE #15660.

GK12D100 0 1 REPLACE EVS CHILD SAFETY SEAT WITH 3-POINT SEAT BELT

Replace the attendant's seat with a new EVS 3-point seat with a built-in child-safety seat.

GSP00001 0 1 SPECIAL INSTRUCTION, INTERIOR COLORS & SEATING

!!! SPRAY ALL THRESHOLDS NORMALLY COVERED WITH ANTI SKID TAPE WITH BLACK SCORPION MATERIAL. DO NOT INSTALL ANTI SKID TAPE.

GSP00002 0 1 SPECIAL INSTRUCTION, INTERIOR COLORS & SEATING

!!! INSTALL MOUNTING PLATES FOR TRANSAFE BARIATRIC WINCH NEXT TO ATTENDANT'S SEAT AND AT FOOT OF PATIENT AREA. DO NOT SUPPLY A WINCH OR RAMPS. DUPLICATE #15660.

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

H1 INTERIOR CABINETRY, STREET SIDE

IG030000 0 1 **SQUAD BENCH SCAB**
Remove and replace the finish floor material from the squad bench scab.

JA INTERIOR CABINETS, FRONT

K1 MODULE INTERIOR ACCESSORIES AND TRIM

L1 COT MOUNTS AND ACCESSORIES

LG03F100 0 1 **COT MOUNT, DUAL: Stryker**
Install Stryker cot mount for dual locations
Cot Model: POWER PRO
Locate: DUAL

M LIGHTBARS FRONT AND REAR

MAM15G00 1 1 **TRANSFER EXISTING LIGHTBAR:**
The current cab-mounted front lightbar is to be transferred to the new unit per instructions below:
!!! REPLACE LENSES WITH NEW CLEAR LENSES.

MM ELECTRICAL EMERGENCY VISUAL WARNING SYSTEMS

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

MM01A000 0 1 WIG WAG HEADLIGHTS:
Install wig wag headlight flasher.

MMSP0010 0 1 SPECIAL INSTRUCTION, VISUAL EMERGENCY WARNING SYSTEMS

!!! REPLACE ALL EMERGENCY LIGHTING WITH WHELEN M SERIES LIGHTING. USE CHROME WHELEN ADAPTOR BEZELS TO CONVERT FROM OLD STYLE LIGHTS TO M SERIES. ALL LENSES ARE TO BE CLEAR. LIGHTS TO BE INSTALLED AS FOLLOWS:

(6) M4 RED, INSTALL (4) IN GRILLE WITH LOWER LIGHTS INBOARD. INSTALL (2) AS CHASSIS INTERSECTION LIGHTS. LENSES ARE TO BE CLEAR.

(1) M7 AMBER, INSTALL OVER REAR DOORS, CLEAR LENS.

(2) M7 RED/AMBER, (2) IN REAR RISER (TO OPERATE WHEN THE REAR DOORS ARE OPEN AND THE IGNITION SWITCH IS 'ON' ONLY),

(2) M7 RED/CLEAR AS WHEELWELL LIGHTS. CLEAR LENSES.

(2) M9 AMBER, REAR AT WINDOW LEVEL, CLEAR LENSES.

(6) M9 RED, (2) CURBSIDE UPPER CORNERS, (2) STREETSIDE UPPER CORNERS, (2) REAR UPPER CORNERS OF BODY, CLEAR LENSES.

MMSP0020 0 1 SPECIAL INSTRUCTION, VISUAL EMERGENCY WARNING SYSTEMS

!!! PROGRAM ALL LIGHTS PER PREVIOUS UNIT 15660.

MN AUDIBLE EMERGENCY WARNING SYSTEMS

MN360000 1 1 TRANSFER EXISTING SIREN HEAD TO NEW VEHICLE
The existing siren shall be transferred from the original vehicle to the new one.
Model:
Locate:

MN45UL00 0 1 SPEAKERS, SA3803
Install SA3803 siren speakers.

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

MN50A000 0 1 SPEAKER INSTALL: bumper
Speaker Selections (Bumper Installed)

MNSP0010 0 1 SPECIAL INSTRUCTION, AUDIBLE WARNING SYSTEMS

!!! NEW CHASSIS IS TO INCLUDE AIRHORNS, HOOD-MOUNTED WITH ACTIVATION THROUGH HORN RING AND A BUTTON ON THE PASS. SIDE OF THE CONSOLE. DISCONNECT AND REMOVE OEM UNDERBODY FRAME MOUNTED HORN.

O LIGHTS

OL09M000 0 1 KKK SIDE BODY MARKER LIGHTS, M6 SERIES L.E.D. (PAIR)
Install red Whelen L.E.D. M6 series turn/marker lights on each rear side of the module body. Lights provide module body night time side lighting visibility and turning signal indication.

!!! USE CHROME WHELEN ADAPTOR BEZELS TO MATCH OTHER BEZELS.

OSP00001 0 1 SPECIAL INSTRUCTION, ELECTRICAL

!!! INSTALL (2) M9 LED SCENE LIGHTS OVER THE REAR DOORS FOR USE AS LOAD LIGHTS. USE CHROME WHELEN ADAPTOR BEZELS TO REPLACE OLDER STYLE LIGHTHEADS.

!!! INSTALL (4) M9 LED SCENE LIGHTS (2) PER SIDE FOR USE AS SIDE SCENE LIGHTS. USE CHROME WHELEN ADAPTOR BEZELS TO REPLACE OLDER STYLE LIGHTHEADS.

PA ELECTRICAL POWER GROUP

PAL00009 1 1 CHASSIS ELECTRICAL HARNESS
A new electrical harness shall be installed on the new chassis. This harness will be custom made to mate up to the existing body.



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

| <u>Option</u> | <u>Std</u> | <u>Qty</u> | <u>Header/Description/Data</u> | <u>Proposal Total</u> |
|---------------|------------|------------|--------------------------------|-----------------------|
|---------------|------------|------------|--------------------------------|-----------------------|

- | | | | | |
|-----------------|---|---|--|--|
| PAL01B00 | 1 | 1 | BATTERY SWITCH: std. operation The "Master" battery switch shall switch battery power "on" and "off" to the ambulance body and conversion added electrical circuits only. All OEM chassis electric's, (headlights, ignition, keep alive) shall remain wired "hot" and have no ability to be switched "off", and provide circuit function as provided by the chassis manufacturer. NOTE: DO NOT MODIFY OEM BATTERY SWITCH UNLESS STATED BELOW. | |
| PAL38C00 | 0 | 2 | SHORELINE: 20 amp eject Install a 20 amp Kussmaul auto ejection shoreline receptacle. Include a dynamic disconnect. <i>Locate: REPLACE EXISTING</i> <i>!!! REPLACE DYNAMNIC DISCONNECTS AS NEEDED.</i> | |
| PL290000 | 1 | 1 | TRANSFER THE EXISTING HAND HELD SPOTLIGHT The existing hand held spotlight is to be transferred from the original chassis to the new one. <i>Locate: PER PREVIOUS.</i> NOTE: DO NOT CUT END OFF OF PLUG. THIS IS TO BE A PLUG-IN STYLE LIGHT. | |
| PSP00001 | 0 | 1 | SPECIAL INSTRUCTION, ELECTRICAL POWER, PROGRAMMING <i>!!! REPLACE EXISTING DOME LIGHTS IN PATIENT HEADLINER WITH CONCEPT STYLE LED DOME LIGHTS.</i> | |
| PSP00002 | 0 | 1 | SPECIAL INSTRUCTION, ELECTRICAL POWER, PROGRAMMING <i>!!! INSTALL 12V POWER UNDER THE SEATBASE PER 15660 FOR THE WINCH SYSTEM. LOCATE CLOSE TO FLIP-DOWN DOOR FOR EASY ACCESS.</i> | |

| | |
|-----------|---|
| QC | HEATING, AIR CONDITIONING AND INTERIOR ENVIRONMENT |
|-----------|---|

- | | | | | |
|-----------------|---|---|---|--|
| QH291A00 | 0 | 1 | REPLACE CABINET MOUNTED HEAT/AC UNIT FOR SWIVEL ATTENDANT SEAT The vehicle heat/ac unit will be installed in the bottom of the linen cabinet instead of the attendant seat base. Requires vertical mounting of a custom combo unit. | |
|-----------------|---|---|---|--|



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

| Option | Std | Oty | Header/Description/Data | Proposal Total |
|--------|-----|-----|-------------------------|----------------|
|--------|-----|-----|-------------------------|----------------|

| | | | | |
|----------|---|---|--|--|
| QH29I200 | 0 | 1 | REPLACE HEAT/AC SYSTEM-COMPRESSOR & CONDENSOR, NAVISTAR, FACE Install a ProAir 12V heat/AC system, complete with compressor and condenser, for the Navistar 4300. Unit is to include a replaceable filter at the air intake point. This system shall not tap into the chassis OEM heat/AC system. Includes a top mounted condenser for DT466. <i>Note: Compressor to be ordered with the chassis.</i> <i>!!! To duplicate previous vehicles.</i> | |
|----------|---|---|--|--|

| R CAB CONSOLE AND COMMUNICATIONS | | | | |
|---|--|--|--|--|
|---|--|--|--|--|

| | | | | |
|----------|---|---|--|--|
| RJ05R000 | 1 | 1 | TRANSFER THE ORIGINAL CAB CONSOLE The original cab electrical console is to be transferred to the new chassis if compatible. | |
| RJ071000 | 0 | 1 | TRANSFER EXISTING RADIO CABLES The existing communication radio cables shall be transferred to the new vehicle. | |
| RJ080000 | 0 | 1 | RADIO POWER/GROUND: Install heavy gauge cable to positive and ground studs for radio power. <i>Locate: Under attendant's seat.</i> <i>Configure: battery switched</i> | |
| RSP00001 | 0 | 1 | SPECIAL INSTRUCTION, CAB CONSOLE & COMMUNICATIONS <i>!!! RELOCATE RADIO FROM LINEN CABINET TO AREA BENEATH ATTENDANT'S SEAT. PROVIDE POWER/GROUND AT THIS LOCATION AS NOTED ABOVE.</i> | |

| TA OXYGEN AND SUCTION | | | | |
|------------------------------|--|--|--|--|
|------------------------------|--|--|--|--|

| | | | | |
|----------|---|---|--|--|
| TN001000 | 1 | 1 | TRANSFER AND RETEST O2 SYSTEM: Transfer the existing O2 system to the new unit and retest. | |
|----------|---|---|--|--|

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Oty Header/Description/Data Proposal Total

| | |
|----------|------------------|
| U | LETTERING |
|----------|------------------|

- UP010000** 0 1 **LETTERING:**
Lettering to be included.
Color: GOLD SCOTCHLITE WITH BLACK SHADE AND OUTLINE
Style: HELVETICA

- UP01CS00** 0 1 **LETTERING REQUIRED ON CURBSIDE OF BODY**
Lettering shall be installed on the curbside of the body. This lettering shall meet the requirements listed below.
NEW STYLE "ESCAMBIA COUNTY" LOGO

!!! UNIT ID NUMBERS ARE 'XX'

- UP01F000** 0 1 **LETTERING REQUIRED ON FRONT OF VEHICLE**
Lettering shall be installed on the front of the vehicle. This lettering shall meet the requirements listed below.
"AMBULANCE" (MIRROR IMAGE ON WINDSHIELD)

"EMS" SIZED TO FIT, UPPER DRIVERS SIDE

!!! UNIT ID NUMBERS ARE 'XX'

- UP01R000** 0 1 **LETTERING REQUIRED ON REAR OF VEHICLE**
Lettering shall be installed on the rear of the vehicle. This lettering shall meet the requirements listed below.
"DIAL 911" (ON REAR DOORS ABOVE WINDOWS)
"BUCKLE UP" (ON REAR DOORS BELOW WINDOWS)

"KEEP BACK" (BOTTOM OF REAR DOORS BELOW STRIPE)
"300 FEET" (SIZE TO FIT)

"EMS" (UPPER LEFT REAR CORNER OF VEHICLE)

!!! UNIT ID NUMBERS ARE 'XX'

ESCAMBIA CO. EMS
6575 NORTH 'W' ST
PENSACOLA, FL 32505
PAT KOSTIC



Selected Feature List 11840

Year: 2015
Chassis: Navistar 102"
Model: CCO 102"

Option Std Qty Header/Description/Data Proposal Total

Total Configured Cost \$167,322.00

Authorized Department Signature(s): _____

